Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: RUTH 28-33 #1-H

Field Name: EAST FORK Well File #: 21045

Date Incident:1/11/2014Time Incident:11:30Facility ID Number:County:WILLIAMSTwp:156Rng:100Sec:21Qtr:

Location Description:

Submitted By: Keith Bryan Received By:

Contact Person: Wade Bragg

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:4 MilesDistance Nearest Water Well:4 Miles

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: Unknown Spilled Units Recovered Units Followup Units

Oil	4	barrels	4	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Description of Other Released Contaminant:

N/A

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Possible inhalation of hydrocarbons during clean up.

Areal Extent:

N/A

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Freshwater valve was locked in the closed position and well was isolated. Clean up activities commenced immediately.

Wastes Disposal Location: Recovered oil being disposed at Newalta. Contaminated soil being

disposed at PDI.

Agencies Involved: N/A

Updates

Date: 1/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, remained on location, according to the report. NDIC retains oversight.